
From: Porfirio Arguellez III/FTEHSF
Sent: Thursday, January 26, 2017 4:28 PM
To: T.P. Tai/TXPO; Jesse Chang/TXLLDPE; Arturo Bazan/FTTRIN; S.C. Chang/TXHDPE; Yu-Lin Kung/FTECCV; Howard Huang/FTHDSF; Robert Marques/FTHDSF; Jingyi Wu/FTP2SF; Albert Blinka/FTP2OR
Cc: Rick Crabtree/FPC Vice President and General Manager; Mike Rivet/TX GMO; Matt Brogger/FTEHSF; I. S. Hwang/ VP Polyolefins Division; Joe Fabrygel/TXMNSF; John Hyak/TXEHS; Chad Lee/FTCFSF; Keith Dickey/FTLLOR; Donnie Long/FTP2OR; Zachary Taylor/FTH2OR; Duane Smith/FTHDOR; Jack Broome/FTHDOR; Matthew Smith/FTLLOR; Akash Shah/FTPPSF; Jon Pape/FTPPSF; Michael A. Pattillo/FTP2OR; Humberto Arguello/FTTRIN; Steve Lee/FTTCSF
Subject: RE: Pellet/Powder Audit 1.26.17
Attachments: Pellet-Powder Audit 1.26.17.pdf

All,
Please see the attached document which entails findings of today's pellet/powder audit.

Thanks,

Porfirio Arguellez III



Environmental Specialist II-Water

Environmental Dept.

Point Comfort, Texas 77978

Office: 361-987-7645

FORMOSA PLASTICS CORPORATION, TEXAS

Traffic Pellet/Powder & Misc.
Observations

Gate 2 Road

Conducted: January 26, 2017

OBSERVATIONS

- PE1/PP1 Bagging/Shipping
 - Pellets observed around door on the north side of the building.
 - Pellets and powder found in ditch north of building.
 - Truck Loading area, pellets and powder observed on pavement as well as on loading ramp.
 - Pellets observed by screens off gate 2 road in front of the bagging/shipping area.

PE1/PP1 Bagging/Shipping Area

ON THE NORTH SIDE OF THE BUILDING JUST ACROSS THE STREET FROM THE PP1 SILOS, PELLETS WERE OBSERVED AT THE BASE OF THE DOOR. FROM INSIDE THE BUILDING A COVER IS IN PLACE TO KEEP PELLETS CONTAINED INSIDE, HOWEVER THERE IS A SMALL GAP WHICH IS ALLOWING PELLETS TO TRAVEL THROUGH.



PE1/PP1 Bagging/Shipping Area

IN THE DITCH NORTH OF THE BUILDING, PELLETS AND DEBRIS ARE VISIBLE IN SEVERAL AREAS.



PE1/PP1 Bagging/Shipping Area

FURTHER EAST FROM PHOTOS OF PREVIOUS SLIDE, POWDER IS VISIBLE IN THE DITCH. PILES OF POWDER HAVE ACCUMULATED IN DIFFERENT AREAS OF THE DITCH.



PE1/PP1 Bagging/Shipping Area

AT THE TRUCK LOADING AREA, PELLETS AND POWDER WERE OBSERVED ON THE PAVEMENT. ADDITIONALLY PELLETS WERE ALSO OBSERVED AT LOADING RAMP 17 (SEE NEXT PHOTO).



PE1/PP1 Bagging/Shipping Area

PHOTO OF PELLETS OBSERVED ON RAMP.



PE1/PP1 Bagging/Shipping Area

JUST OFF GATE 2 ROAD IN FRONT OF THE BAGGING/SHIPPING AREA, PELLETS WERE OBSERVED UP ALONG THE SCREENS WHICH ARE IN PLACE TO KEEP PELLETS FROM ENTERING THE DITCH.

