
From: Porfirio Arguellez III/FTEHSF
Sent: Friday, March 10, 2017 3:43 PM
To: T.P. Tai/TXPO; Jesse Chang/TXLLDPE; Arturo Bazan/FTTRIN; S.C. Chang/TXHDPE; Yu-Lin Kung/FTECCV; Howard Huang/FTHDSF; Robert Marques/FTHDSF; Jingyi Wu/FTP2SF; Albert Blinka/FTP2OR
Cc: Rick Crabtree/FPC Vice President and General Manager; Mike Rivet/TX GMO; Matt Brogger/FTEHSF; I. S. Hwang/ VP Polyolefins Division; Joe Fabrygel/TXMNSF; John Hyak/TXEHS; Chad Lee/FTCFSF; Keith Dickey/FTLLOR; Donnie Long/FTP2OR; Zachary Taylor/FTH2OR; Duane Smith/FTHDOR; Jack Broome/FTHDOR; Matthew Smith/FTLLOR; Akash Shah/FTPPSF; Jon Pape/FTPPSF; Michael A. Pattillo/FTP2OR; Humberto Arguello/FTTRIN; Steve Lee/FTTCSF
Subject: RE: Pellet/Powder Audit 3.10.2017
Attachments: Pellet-Powder Audit 3.10.17.pdf

All,
Please see the attached document which overviews today's pellet/powder audit.

Thanks,

Porfirio Arguellez III



Environmental Specialist II-Water

Environmental Dept.

Point Comfort, Texas 77978

Office: 361-987-7645

FORMOSA PLASTICS CORPORATION, TEXAS

Traffic Pellet/Powder & Misc.
Observations

Gate 2 Road

Conducted: March 10, 2017

OBSERVATIONS

- TECHNICAL
 - Pellets observed around dumpsters.
- LLDPE WAREHOUSE
 - Pellets observed under and around plastic pallets.
- PP-1
 - Powder and pellets observed in two different sections of ditch.
- PE1/PP1 BAGGING/SHIPPING.
 - Pellets observed under mouser container and pavement by overhead door.
 - Pellets and powder observed in section of ditch on east side of building.
- PE1/PP1 RAILCAR LOADING
 - Pellets observed on pavement in hopper car cleaning area.
 - Pellets observed in sump on south side of loading area.

TECHNICAL

ON THE SOUTHEAST CORNER OF THE TECHNICAL LAB BY THE DUMPSTERS, A PILE OF PELLETS WAS OBSERVED ON THE PAVEMENT.



LLDPE WAREHOUSE

JUST OUTSIDE THE WAREHOUSE, PELLETS WERE OBSERVED UNDERNEATH AND AROUND THE STACKS OF PLASTIC PALLETS.



PP-1

NORTHWEST OF THE COOLING TOWER, POWDER DEBRIS LINE IS VISIBLE ALONG CONCRETE PAVEMENT.



WEST SIDE OF THE PROCESS AREA, POWDER AND PELLETS WERE OBSERVED ON PAVEMENT AROUND CULVERT.



PE1/PP1 BAGGING SHIPPING

PELLETS WERE VISIBLE UNDER THE MOUSER CONTAINER WHICH IS STAGED UNDER THE SILOS AT THE BAGGING/SHIPPING AREA.



PE1/PP1 BAGGING SHIPPING

ON THE WEST SIDE OF THE BUILDING, PELLETS WERE OBSERVED ON THE PAVEMENT PRIOR TO ENTERING THE BUILDING.



PE1/PP1 BAGGING SHIPPING

ON THE EAST SIDE OF THE BUILDING, POWDER & PELLETS ARE VISIBLE IN A SECTION OF THE DITCH.



PE1/PP1 RAILCAR LOADING

IN THE HOPPER CAR CLEANING AREA, PELLETS WERE VISIBLE ON THE PAVEMENT.



PE1/PP1 RAILCAR LOADING

ON THE SOUTH SIDE OF THE LOADING AREA, PELLETS ARE VISIBLE IN THE SUMP.

